## Air Ionizer Verification Record

WORKING STANDARD USED Asset/ISO #: Calibration Date: Calibration Due: Calibration By: Manufacturer: 6779 8/8/07 8/8/28 TPL TON 775 25171 AIR IONIZER INFORMATION Verification Date: Verification Due: Verification By: Serial No. Asset/ISO #: Manufacturer: Model: 33674328T 3-19-08 LCOSTAT PC 7-11-08 28301 CINCO Owner: John Fail: Y/N? Cleaned: Y/N? Adjusted: Y/N ? Prior Sequence# Inspector: 317/STH-IPT2 Magripusti Minh N NA VERIFICATION DATA 50V HBM Sensitivity Level: (from Table 1) Fan controller setting: Distance of ionizer from the charge plate: ± 50 Vdc. Ionizer Float Potential Tolerance Measured Float Potential values recorded below. Comments: \_10 Vdc. \_10 Vdc. \_20 Vdc. -10 Vdc. \_10 Vdc. Ionizer Discharge Voltage Range: ± 1000 Vdc to < ± 50 Vdc (from Table 1) Ionizer Discharge Time Tolerance: (20 seconds. (from Table 1) Measured Discharge Time in second(s) and recorded values below. 1 (+1000 to +Vdc) 2 (+1000 to +Vdc) 3 (+1000 to +Vdc) 4 (+1000 to +Vdc) 5 (+1000 to +Vdc) Comments: 3. Z sec 3.0 sec 3 (-1000 to -Vdc) 4 (-1000 to -Vdc) 5 (-1000 to -Vdc) 1 (-1000 to -Vdc) 2 (-1000 to -Vdc) Comments: 4.4 sec 5.0 sec 5.1 4.9 Record any corrective action required to restored ionizer operation (cleaning, adjustment, replacement, etc.) If Ionizer was replaced, indicate below the identification of replacement. Asset/ISO #: Manufacturer: Model: \_\_\_\_\_ Serial No.: \_\_\_\_\_ Sequence number for verification of replacement Ionizer: Record inspection schedule and rational for that schedule.